

Pending/Incomplete work

Files

Wood work

- ① Main door locks/handles, lense
- ② Door Stoppers (magnet), pooja door polish, any door problems.
- ③ After Maddi, leakage in parking (near pipe/beam), bathroom corners, @ Slope problems.
- ④ Skin door problems for BR, bathroom doors. (5) bathroom doors/any frame problem (peeling)

Electric work

- ① GF - Regulator in bedroom
- Regulator problem in hall
- MCB missing in DP.
- ② 2 way lights, 2 tray fans.
- ③ Zero bulb holders - all rooms.
- ④ Gysar connection point near Gysar. - I flr
- ⑤ Gysar button inside bathroom - like GF.
- ⑥ DP changes.
- ⑦ Calling bells

Plumbing work

- ① GF, FF, SF - Wash basin (Total 4 WBS).
- ② Tap & wash basin @ Western.
- ③ GF Kitchen side chamber - No plate.
- ④ ~~Karezi tap @ SF~~ (5) Leakage @ basin exit @ FF Kitchen

Tiles

- ① Fill all gaps - tiles, walls, stairs etc.
- ② Kitchen both sides filling - FF
- ③ proper slopes in balconies, stairs, near main door.
- ④ proper slope for Kitchen Slabs (6) Gate Stoppers & holes.
- ⑤ Granite Slab crack @ SF.

Civil work

- ① Water plugging from terrace/top stairs.
- ② parking - chamber plastering from stair-case gaps.
- ③ GF chamber plate for kitchen side chamber.
- ④ Scum - water proof.

Painting work

- ① All damaged paint for walls, grills/stairs, slabs
- ② I flr - BR wardrobe gap filling
- ③ I flr - Bedroom Slab painting

Any other problems

- Valve for parking tap, lysar @ western.
- Wood work → sharp door edges, bathroom doors tape.
- Lysar hole → glass sharp edges
- Bedroom locks, check all drawers.
- Electric
 - BR1 - fan regulators, DP chokes, BR2 - regulator
 - Lysar point
 - Iffr - wash light button outside, EF hall 3-pin no on/off.

wood work:

- window bottom, main door sharp edges
- Kitchen side wall - cemented.

- (1) Fill all gaps
- (2) Kitchen both sides filling - EF
- (3) Proper slopes in balconies, stairs, near main door.
- (4) Proper slope for kitchen slabs

Needs use of...

- 1) Regulator in Hall, BR - GF
- 2) No...

T... 469730

- BR door keys - fert
- Kitchen door touching each other ✓
- Balcony door gap
- Bathroom - fibre slab fix ✓
- Door bottoms - sharp
- BR1 - cupboard lock issue.
- main door lock
- Hole for pot area (near gate)
- Sharp corners - grills

Tiles

- Wall tiles gap filling
- main/balcony door edge gaps
- Wash basin gaps
- Slopes
- Iffr wall/tiles cracks
- Chpl stand granite
- parking side tiles
- GF - Gas pipe hole